

WIRING AND ACTUATOR CONTROLS FURNISHED BY OTHERS. 240 VOLT, 1 PHASE POWER SUPPLY REQUIRED.